

---

Subject: Re: linn, Direct Drive, homebuilds  
Posted by [Manualblock](#) on Tue, 27 Apr 2004 18:49:50 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Any chance you had phase issues there? Check the phono jack wiring maybe, just guessing.

---