

---

Subject: Re: Dual 505-4 help needed

Posted by [Wayne Parham](#) on Mon, 31 Jan 2005 05:45:13 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I see. When you stop the platter or increase drag on it, this makes the motor draw more current. That leads me to believe that you might have a ground loop that is causing motor power current draw to introduce noise onto the signal line. Have you tried isolating the cartridge signal wires? Are any of those four wires connected to the chassis? Could one of them be touching?

---