

---

Subject: First Upgrade

Posted by [FredT](#) on Fri, 30 Sep 2005 15:40:13 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I replaced the resistor in the CRC tube section high voltage power supply with a 10 henry choke and applied chassis damping material to the top cover and accessible areas inside the chassis.

Picture at <http://fredt300b.smugmug.com/gallery/132868/1/38101224>

Inside the Lite Audio DAC-60

---