

---

Subject: Re: Isobaric

Posted by [Wayne Parham](#) on Wed, 16 Feb 2005 03:49:07 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I expect that the subwoofer output on your receiver is a 0.775v preamp level output. It is probably limited to 80Hz or 100Hz. Try connecting another amplifier between the subwoofer output and your speakers and see if that works.

---