

---

Subject: Re: K1840 for consultation

Posted by [Jim Griffin](#) on Wed, 04 May 2005 13:52:14 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Bill,I really thinking that power tapering needs to be symmetrical with less power going to the outer drivers. Now as I have said power tapering needs to be an adjustment which balances the power injected into the room at the low end of the frequency band. So take care to work the power/room balance equation.Jim

---