

---

Subject: Re: The VMPS Neo Ribbon Driver - Anyone Ever Measure One ?  
Posted by [Danny Richie](#) on Tue, 06 May 2008 01:00:54 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The low crossover point was one of the problems. Keeping the drivers acoustically in phase with one another was the other issue that they had. I crossed the planar mids in the 650Hz to 700Hz range and this was about as low as they really liked playing. This was also to a smaller woofer and with steeper slope than what was used in the VMPS speakers. So they didn't have phase related issues.

---