

---

Subject: Re: AVT150

Posted by [Wayne Parham](#) on Mon, 27 Jun 2005 03:50:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Could also be that the amplifier outputs should be isolated and not connected to earth ground.  
What fuse is blowing?

---