
Subject: Re: Fender Bandmaster Vibrato Problem
Posted by [Thermionic](#) on Tue, 21 Feb 2006 03:33:07 GMT
[View Forum Message](#) <> [Reply to Message](#)

Yep, 12AY7s don't have enough gain to oscillate in Fender vibrato/tremolo circuits. I forgot about that, it could be an improper tube causing the problem in the Bandmaster. Thermionic
