

---

Subject: Re: Attn:BillW

Posted by [lelandcrooks](#) on Tue, 17 Oct 2006 19:10:13 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Yea, that's what I was looking at also. It seems to me it's got to be driver related. Even the narrow box shouldn't drop that fast, especially when you started running multiples and the mouth area expands. They've got to be unloading at that point, which with the narrow box makes sense, and the ev's don't have the guts to go into dr mode and pickup the difference.

---