

---

Subject: lower mu...

Posted by [PakProtector](#) on Mon, 14 Mar 2005 11:05:33 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Nope, you have it. A few more LED's will be all. More current is a 'tweak' level of change. 6 or so LED's and another socket will be all that is required. You'll be pulling a little bit more heater current. Still going to be 12.6, but at 0.6 A instead of 0.5 A. Some tweaking of the R's in filament supply might be needed if you want exactly 12.6. 12-13 ought to be fine IMO...The 12B4's are mu 6.5 and until you increase heater current or get octal valves, it is the best. Maybe the best without caveats. regards,Douglas

---