

---

Subject: 6A5 P-P # 2

Posted by [Forty2wo](#) on Sat, 23 Sep 2006 02:57:18 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The sockets and a few other bits are mounted, two sets of filament wiring, 12V for the driver. The drivers are wired up. Normally I build the power supply first but once I mount the power transformer things will start to get heavy...John

---