

---

Subject: Solution near

Posted by [Art J.](#) on Sun, 08 Apr 2001 12:15:22 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I believe I found the cause of the 45d phase shift. I have to find time today to re-configure the xover to confirm my tests. Stay tuned.....BIG HINT:The Woofer is 4 OHM ( 2 - 8 ohm woofers in parallel)The mid is 8 OHM I never presented the "big picture" of the situation. That was an error of ohm-missions on my part. Im a terrible writer.A Tip for Hobbyist;All my cross-over parts are mounted on 'screw down' terminal strips to make it easy to re-configure and change parts.

---