

---

Subject: Re: Doh! Sorry to get your (and my) hopes up, but...

Posted by [Mike Borzcik](#) on Sat, 01 Sep 2001 22:43:39 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I checked my crossovers again, and I did indeed use 0.47 uF capacitors in the compensation network. I just read them wrong when I posted the description of the assembly. So that's unfortunately not the problem. Maybe once I get pictures of the crossovers there will be something that I missed in my written description. The problem could also be the acoustics of my room. I'm in a pretty small dorm room and the speakers are right next to each other. I can sit up to eight feet away from the speakers, but I'm still directly in front of both of them. Could being directly on-axis cause some of the horn sound? They do sound pretty good, so I still think that maybe I'm just being too picky. I'm still hoping that there's something wrong with them, though. :-)