Subject: Re: I was going to use...Unfortunately..... Posted by BillEpstein on Fri, 01 Mar 2002 19:44:32 GMT View Forum Message <> Reply to Message

Two problems:1) The 1/4 20 are too thick to go thru the slots w/o forcing them, and the heads are small(see #2) 2) #10-32 are the right size bolts but the heads so small they go right thru the soft material of the horn when you tighten them down. We need to find #10-32 with the oversize pan head JBL uses. Even black washers are unsightly.

Page 1 of 1 ---- Generated from AudioRoundTable.com