

---

Subject: Re: Horn flare survey

Posted by [Garland](#) on Sat, 13 Apr 2002 07:21:24 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The H 290 worked for me but there was the problem of the bolt holes for mounting the driver needing modification to get the bolts through. That may be a problem for some DIYers and a problem in customer satisfaction for you!G.