
Subject: That's the most common cause of this symptom
Posted by [Wayne Parham](#) on Wed, 02 Oct 2002 01:59:19 GMT
[View Forum Message](#) <> [Reply to Message](#)

I suspect the tweeter compensation cable assembly was built improperly. After we get a response, we'll probably know.