

---

Subject: Re: Still more Theater 4 tweaking...

Posted by [Neo](#) on Wed, 16 Oct 2002 17:34:38 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Garland, Is it the tweeter coil you changed? It must be because the woofer coil is 1mH. I upgraded all my crossover components, except the tweeter coil. Hmmmm... and that makes a difference? It's not directly in the signal path... I wonder why ? If you found a positive difference, I'll give it a try. Thanks for the info... Tom - (remember me... we talked at the meeting at DRCope's place. I brought my rebuilt Pi 4 crossovers.)