

---

Subject: error in "bench" schematic

Posted by [Sam P.](#) on Fri, 31 Jan 2003 16:34:52 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

is why Wayne needed to slap R17 in there. C3 is labeled 0.01u, it SHOULD be 0.001uF. Just correcting the value of C3 changes his LP response from peaky to nice:) Sam

---