

---

Subject: Thx Wayne

Posted by [mollecon](#) on Thu, 10 Jul 2003 21:57:20 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I guess it's the lack of sealing that makes it possible for the fluid to evaporate when the unit is driven hard - the D28's aren't build that way! :-)

---