

---

Subject: Re: Pi Alignment ?

Posted by [Wayne Parham](#) on Fri, 12 Aug 2005 06:36:38 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

It's best to measure the T/S electro-mechanical parameters, and use the reciprocal of Qts as Qd.

---