

---

Subject: Re: Larger Driver

Posted by [Zene Gillette](#) on Mon, 04 Sep 2006 04:11:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Wayne ... It's not the terminals it's the leads that connect directly to the vc. Explanation was they don't have strain relief so they vibrate until they break. Eminence is aware of problem so is not minor. Can send you one if it's of any importance. Might not be if you've had no problems. Zene

---