

---

Subject: Re: Dedicated horn loaded mid -- big disappointment.  
Posted by [Wayne Parham](#) on Tue, 13 Oct 2009 05:02:56 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hard to say without seeing measurements. Could be a sensitivity mismatch, since the midhorn is probably something like 105dB/W/M and the rest of the drivers are probably at least 10dB less sensitive. Or it could be that there are pipe modes down low. Is there any way for you to make measurements to see which it is?

---