

---

Subject: Re: Just received a set of 2 Pi's ...

Posted by [Wayne Parham](#) on Sun, 04 Apr 2010 00:57:53 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

There should be a 0.5mH coil in series with the woofer. If it isn't there, install one. The upper midrange is a little too strident without it.

provides adequate bass. But the towers reach a full octave lower. As mains, I think you'd be much happier with towers if you don't have subs.