Subject: Re: 7Pi Build 2014 Posted by tubemax on Sun, 14 Sep 2014 09:03:10 GMT View Forum Message <> Reply to Message

It looks like 150hm damping resistor is also not connected to the ground?

Max

File Attachments
1) 7pi+X0 II.jpg, downloaded 315 times

Page 1 of 1 ---- Generated from AudioRoundTable.com