
Subject: Re: 7Pi Build 2014

Posted by [tubemax](#) on Sun, 14 Sep 2014 09:03:10 GMT

[View Forum Message](#) <> [Reply to Message](#)

It looks like 150hm damping resistor is also not connected to the ground?

Max

File Attachments

1) [7pi+XO II.jpg](#), downloaded 302 times
