

---

Subject: Re: 8 years later

Posted by [Wayne Parham](#) on Mon, 07 Feb 2022 16:30:55 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

across C4 is exactly right. That tells me the coil didn't get pressed down onto the PCB traces, which is the most common culprit for symptoms like these.

---