Subject: Re: Scott 299C and 7591 tubes
Posted by real_one on Mon, 19 Nov 2007 15:20:40 GMT
View Forum Message <> Reply to Message

Check to make sure you didn't blow a capacitor. If so, replace it. If not, enjoy!