Subject: Re: AR Pulley
Posted by martinleewin on Thu, 24 Jun 2004 15:14:25 GMT
View Forum Message <> Reply to Message

Thanx Wayne,I found Joel @ The Turntable Factory. He is sending one "for a favor to be returned later" maybe Scott amp & tuner restoration work I do. The dimensions confirm the problem was a 50 Hz pulley.Martin W.