Subject: Pioneer PL-100 problems
Posted by Troy James on Sat, 08 Oct 2005 12:26:27 GMT
View Forum Message <> Reply to Message

Hi. I have the above turntable. It is about 20 years old and belt driven. I had the old belt (which had perished from lack of use) replaced recently at a Pionner Shop. But the stroboscope will not line up and jumps eractically when adjusted. Any idea what the problem is and how I can solve it?Cheers