Subject: Re: Two turntables, two problems
Posted by hurdy_gurdyman on Thu, 28 Dec 2006 20:42:25 GMT
View Forum Message <> Reply to Message

Sounds like a new belt would take care of the speed problem. The tracking forse of the tonearm should either have a dial on the pivot structure and/or the couter-weight should be adjustable, probably by rotating it. Most Duals had both.
http://www.compassnet.com/concept/tables/CS415-2.htmhttp://www.compassnet.com/concept/tables/cs410.htmhttp://www.dual-reference.com/Dave