Subject: Re: Horrible
Posted by Mike.e on Mon, 09 May 2005 01:25:39 GMT
View Forum Message <> Reply to Message

So The answer would be-to shift the acoustical axis downwards through xover changes/driver positioning?I've got to get back to working on the bathroom remodel - I think my wife has almost run out of patience with this project.Well atleast you have it up and running for tweakage later..Mike.e