Subject: Re: Sprinkling posts...
Posted by akhilesh on Thu, 15 Jul 2004 23:23:15 GMT
View Forum Message <> Reply to Message

Hi Robert,Maybe the driver cones absorbed some moisture and became "doped" in some way. I know a lot of builders dope them anyway.Just a hypothesis. -akhilesh