Subject: Re: Newest acquisition 2 - 8" full range from Roland
Posted by roncla on Wed, 15 Sep 2004 21:59:08 GMT
View Forum Message <> Reply to Message

Must be my program as i see an increasing pressure at the top as the cone moves inward.Then i see an expanding pressure front from the pointed end which arrives at the port later in time than the driver point.Harmonic?ron