Subject: Re: Isobaric
Posted by Wayne Parham on Wed, 16 Feb 2005 03:49:07 GMT
View Forum Message <> Reply to Message

I expect that the subwoofer output on your receiver is a 0.775v preamp level output. It is probably limited to 80Hz or 100Hz. Try connecting another amplifier between the subwoofer output and your speakers and see if that works.