Subject: a lack of "air" at the treble extremes
Posted by Marlboro on Fri, 07 Mar 2008 23:55:10 GMT
View Forum Message <> Reply to Message

Indicative of comb filter distortion starting at 12Khz, and which cannot be "fixed" with equalization.