Subject: Re:Put de lime in de coconut.....
Posted by Bill Martinelli on Sat, 09 Apr 2005 18:16:11 GMT
View Forum Message <> Reply to Message

I like a combination of both these guys. Apply a heavy coat and wipe most of it off after 1o minutes. then when the surface gets tacky in another 15 or 30 minutes. I rub it down hard with a clean soft rag to burnish the shine. If you apply another coat before the preceding coat hardened, then you end up re-dissolving, so to speak, the coat you just put on and don’t get as much build up as if you wait 4 hours to overnight. A fan can help speed things along.After two coats I use either fine steel wool or 600-1500 paper and smooth of the surface again. You can keep doing this until you’re happy with the finish.