Subject: Solution near
Posted by Art J. on Sun, 08 Apr 2001 12:15:22 GMT
View Forum Message <> Reply to Message

I believe I found the cause of the 45d phase shift. I have to find time today to re-configure the xover to confirm my tests. Stay tuned.....BIG HINT:The Woofer is 4 OHM (2 - 8 ohm woffers in parellel)The mid is 8 OHMI never presented the "big picture" of the situation. That was an error of ohm-missions on my part. Im a terrible writer.A Tip for Hobbyist;All my cross-over parts are mounted on 'screw down' terminal strips to make it easy to re-configure and change parts.