Subject: Thx Wayne
Posted by mollecon on Thu, 10 Jul 2003 21:57:20 GMT
View Forum Message <> Reply to Message

I guess it's the lack of sealing that makes it possible for the fluid to evaporate when the unit is driven hard - the D28's aren't build that way! :-)