Subject: Re: Adjusting the capacitor value on the tweeter attenuator
Posted by Wayne Parham on Sat, 16 Aug 2003 19:50:53 GMT
View Forum Message <> Reply to Message

Are the cables installed so that the components are nearest the crossover circuit board? I'm sure you have that part right. But I can sure hear the difference when capacitor C1 is removed, so something is up. Let's get together sometime soon and have a look at them. Maybe the cables assemblies are built wrong. I'll look over the ones in inventory too - They're built in batches, so if yours are wrong, probably a couple of others are too.