Subject: Numero 6 heads too small
Posted by Ubu on Thu, 09 Oct 2003 10:14:21 GMT
View Forum Message <> Reply to Message

the #6 heads are too small for the alpha 10 holes - not a tight fit.