Subject: Compensation Network connection

Posted by HaknHendrix on Wed, 24 Mar 2004 01:53:05 GMT

View Forum Message <> Reply to Message

About to solder the tweeter compensation resistors together, along with the capacitor. I hope this diagram is understanble, but want to make sure I've got it before I commit solfer.The diagram below should represent 4 pairs of 16 ohm resistors in parallel serial combination.Top View of Resistor Pack   O----O----O----O   O----O----O----OBottom View of Resistor Pack

  T1------O----O   O----O-----C3 | | T2------O----O   O----O | |

   |-||-| C1ThanksHakn