Subject: My Eminence Kappa 12 just quit on me :-(
Posted by Magnus on Sat, 14 Aug 2004 10:30:06 GMT
View Forum Message <> Reply to Message

Now this is strange. When I swithed on the stereo this morning there was no bass/midrange in the left channel of my biamped system. One of the Eminence Kappa 12's had apparently gone south. Neither any DC resistance across the voice coil nor any visible sign of damage. Quite strange for a driver that is rated at 450 W RMS and have been operated with a few watts and well below Xmax. This is really one of those "what could possibly go wrong" situations.How is the aluminum voice coil attached to the tinned copper leads? Is there some sort of crimp connection here that could break?/Magnus