Subject: Re: I'm working on that boxiness
Posted by Bill Epstein on Sun, 13 Aug 2006 12:15:22 GMT
View Forum Message <> Reply to Message

Kind of a 'hollow' sound.I took apart the third order BW and left it crossed at 3000 with just the 13.25 cap first order. Then swapped out the 1 mH coil replaced it with .5 on the woofer. Textbook. We'll see if that helps.