Subject: Tweakin' agin
Posted by Bill Epstein on Sat, 22 Dec 2007 15:43:51 GMT
View Forum Message <> Reply to Message

Have a pretty nice integrated amp in for review and it intermittently distorts with lower dBs on one channel. The M sent me a set of new tubes. Trouble-shooting pointed to them but also could have been the crossover.I've meant to rebuild the Eminence 1.6ks for some time and this was a good excuse. Removed the compnents from the PCB and caulk'd em to a piece of plywood.That included a set of Edison Price Muisc Posts that had already proved thir worth along with Obbligato oils, a Jantzen 8.0 from PE and a honlin' big 15ga. Jantzen .6mH tweeter coil. No more connectors; all point-to-point.Crossover sounds great and definitely not the culprit.Now the amp is playing fine having been distorting on first try. That makes a tube problem doubtful. More likely an SMD, especially the Dact attenuator.Enjoying Laura Nyro while it stays working right.Have a Tweakin' Good Christmas, all!