Subject: 12Pi v2
Posted by Roland Gama on Mon, 18 Feb 2008 13:10:08 GMT
View Forum Message <> Reply to Message

Hello Wayne,There seems to be an error with the external panels measurement.The plans show that the 45 degree cut on the external panels begin at 38-7/32 from the edge of the mouth opening while all other panel cuts makes this one to be 36-3/8 (ie a difference of about 2 inches.) for things to click in place. Am I right?Roland.