Subject: Re: Pioneer RT-909
Posted by timestar on Fri, 08 Jan 2010 19:59:01 GMT
View Forum Message <> Reply to Message

Thanks, Wayne. I'll check the pinch rollers, but I think they are new. What kind of adjustment did yours need? I'm told by local repair that it is probably a problem on the DC board at a cost of $250.
Robert