Subject: Re: philco 48-1253
Posted by capbuster on Sat, 14 Aug 2010 16:32:41 GMT
View Forum Message <> Reply to Message

My concern is it is a original can cap. It has two leads on bottom
neg. & pos. The neg goes into can positive lead just there going to nothing. Soldered to lead on bottom of can but nothing else there.
Thanks Capbuster.