Subject: Re: Pro-Ject Debut III Noise with Speed Box
Posted by Wayne Parham on Tue, 03 May 2011 23:49:45 GMT
View Forum Message <> Reply to Message

My guess is the motor was bad from the get-go. Shouldn't have any problems with just 200 hours on it. Turntables don't put any unusual loads on the motor, not much load of any sort.