Subject: Re: 8 years later
Posted by Wayne Parham on Wed, 26 Jan 2022 22:54:30 GMT
View Forum Message <> Reply to Message

It's definitely odd that both act the same way.

But regardless, let's just step through the troubleshooting procedure. Using an ohmmeter, measure across the following terminals and report back what you see:

1. Measure from IN- to 2- and find zero ohms.
2. Measure from IN+ to 2+ and find 4.5 ohms.
3. Measure from 2+ to 2- and find 8 ohms.