Subject: Re: Scott 299C and 7591 tubes
Posted by Forty2wo on Mon, 19 Nov 2007 22:30:37 GMT
View Forum Message <> Reply to Message

The crackle and pop may just be dirty sockets. The act of removing and replacing the tubes cleans them to a degree. If you plan to use it on a regular basis I would consider replacing the electrolytic caps and maybe upgrading the bias supply…John